



Photo #1: Site conditions upon arrival 10-23-13; valley gutter looking southeast



Photo #2: Site conditions upon arrival 10-23-13; west ditch of Truck Street



Photo #3: Exposed propane line and product line; 10-23-13; looking north



Photo #4: Exposed propane line and product line; 10-23-13



Photo #5: Test pit south of sidewalk; 10-23-13; looking north



Photo #6: Test pit locations, south of sidewalk; 10-23-13; looking west



Photo #7: Pits excavated along east side of building; 10-23-13; looking north



Photo #8: Accumulated product in pit overnight; 10-24-13; looking north



Photo #9: Saturated soil removed adjacent to south edge of sidewalk; 10-24-13; looking northwest



Photo #10: Saturated soil removed east of building; 10-24-13; looking north



Photo #11: Saturated soil removed south of valley gutter; 10-24-13; looking southeast



Photo #12: Saturated soil removed from ditch; 10-24-13; looking south



Photo #13: Backfilling; 10-24-13; looking west



Photo #13: Backfilling; 10-24-13; looking south



Photo #14: Booms deployed in ditch to catch residual run-off; 10-24-13; looking south



Photo#15: Area looking Northwest