



## INCIDENT INVESTIGATION #209087

---



Oneida and Pleasant, Pierre, SD

### LOCATION DETAILS

**Event Date:** 06/01/2021 04:11 PM America/Denver

**Right-of-Way:** City Street

### AFFECTED FACILITY

**Near Miss:** No

**Type of Operation Affected:** Gas

**Line Size and Type:** 2.00" Plastic

**Facility part of joint trench:** No

**Asphalt or concrete removed:** No

**Damage Surface Type and Depth:** Dirt 18" - 36"

**Arrival Date and Time:** 06/01/2021 04:25 PM America/Denver



**Distance from Ped to Ped:** 0ft

**Dimensions of Asphalt or Concrete Removed:**

**Repairs Taking Place Upon Arrival?** No

**Who Performed Repairs:** Utility Company

**Contractor Representative:** Josh Larson

**Contractor Representative Phone Number:** (605) 223-3245

**Personnel On Site:** 2 technicians for MDU

**Vehicles/Equipment Being Used For Repairs:** 2 Trucks / Hand tools

**Guards or Barricades On Site:** 3 sets of fire trucks blocking 3 different intersections

**Facilities Replaced or Repaired:** Repaired

**Replacement Type:** Permanant

**Occurred During:** Business Hours

**Time Occurred:** 4:11 PM America/Denver

## **DAMAGER**

**Company Name:** Anderson Contracting

**Contact:** Josh Larson

**Contact Phone:** (605) 223-3244

**Type of Work:** Curb and gutter replacement

**Damage Responder:** Kevin, Anderson

## **UTILITY INFORMATION**

**Utility Company Name:** Montana Dakota Utilities

**Utility Contact Name:** Tye

**Utility Contact Phone:** (605) 222-1740

**Utility Representative:** Tye

**Utility Rep Tech#:**

**Utility Rep. Present on Arrival:** No

## **EXCAVATION INFORMATION**

**Excavator Type:** Contractor

**Excavation Equipment:** Backhoe/Trackhoe

**Work Performed:** Curb/Sidewalk

**Excavator downtime?** Yes

**Downtime hours:** 1

**Downtime cost:** No

## **NOTIFICATION AND LOCATING**

**One Call Center notified:** Yes

**Locator Type:** Contract Locator

**Work area white-lined:** No

**Ticket Number:** 2114816873

**Date Located:** 06/01/2021 10:44 AM America/Denver

**Located By:** Erin Harrington

## **INTERRUPTION AND RESTORATION**

**Event cause Interruption:** Yes

**Interruption hours:** 1

**Customers Affected (approx.):** 2

## ROOT CAUSE

**Root Cause:** Excavator dug prior to verifying marks by test-hole (pot-hole)

## COMMENTS

**Assessment Comments:** 2" gas main was damaged by Anderson Contracting . Gas main was marked accurately no deviation at all. Contractor did not look for gas before digging and hit the gas main with his bobcat. Gas was blowing and fire department and police officers were on site. 811 was notified. Contractor was also digging before the legal start time.

# INCIDENT AND SURVEY COMPARISON PHOTOS

## SURVEY PHOTO



Ticket: 2114816873.0 Timestamp:6/1/2021 1:13:52 PM

Date: 06/01/2021 01:13 PM  
America/Denver

Latitude: 44.370833

Longitude: -100.357500

Heading: 177 degrees

## INCIDENT COMPARISON PHOTO



Date: 06/01/2021 03:52 PM  
America/Denver

Latitude: 44.371166

Longitude: -100.357522

Heading: 228 degrees

## SURVEY PHOTO



Ticket: 2114816873.0 Timestamp:6/1/2021 1:13:52 PM

Date: 06/01/2021 01:13 PM  
America/Denver

Latitude: 44.370833

Longitude: -100.357500

Heading: 177 degrees

## INCIDENT COMPARISON PHOTO



Date: 06/01/2021 04:46 PM  
America/Denver

Latitude: 44.371118

Longitude: -100.357661

Heading: 215 degrees

## NEW INCIDENT PHOTOS



Date: 06/01/2021 03:52 PM  
America/Denver

Latitude: 44.371163

Longitude: -100.357581

Heading: 216 degrees



Date: 06/01/2021 03:52 PM  
America/Denver

Latitude: 44.371177

Longitude: -100.357607

Heading: 218 degrees



Date: 06/01/2021 03:54 PM  
America/Denver

Latitude: 44.371210

Longitude: -100.357644

Heading: 210 degrees



Date: 06/01/2021 03:54 PM  
America/Denver

Latitude: 44.371181

Longitude: -100.357665

Heading: 223 degrees





Date: 06/01/2021 03:55 PM  
America/Denver

Latitude: 44.371181

Longitude: -100.357665

Heading: 223 degrees