

Mail completed form to:

PUBLIC UTILITIES COMMISSION
500 EAST CAPITOL AVENUE
PIERRE, SD 57501
ATTN: SOUTH DAKOTA ONE CALL BOARD

0004-001

RECEIVED

JAN 22 2004

SOUTH DAKOTA PUBLIC
UTILITIES COMMISSION

COMPLAINT


COMPLETE INFORMATION IS REQUIRED - ADDITIONAL PAGES MAY BE USED IF REQUIRED

ALLEGATION OF PROBABLE VIOLATION(S) OF SOUTH DAKOTA ONE CALL LAWS

I. ACTION REQUESTED BY:

COMPLAINT FILED BY INDIVIDUAL OR BUSINESS* PERSON FILING COMPLAINT (Please print): Scott Harkless

COMPANY (If applicable) Golden West Telecommunications Coop, Inc. ADDRESS 1510 National ave Hot Springs PHONE NUMBER 605-745-3103

SIGNATURE OF COMPLAINANT:  DATE: 1-20-04 EMAIL ADDRESS: scottharkless@goldenwest.com

*If the complaint is files on behalf of a Company, the person signing this form should have the proper authority to file the complaint.

II. ACTION REQUESTED AGAINST:

NAME OF EXCAVATOR/FACILITY OPERATOR: Olander contracting co PHONE NUMBER: 701-232-6716

ADDRESS: 3155 44th ave NW Fargo, ND 58107

WAS A LOCATE REQUESTED FROM SD ONE CALL? YES NO LOCATE TICKET #: 040190075

START DATE ON TICKET: 1-22-04

DID EXCAVATOR WAIT UNTIL THE START DATE/TIME ON THE TICKET BEFORE COMMENCING EXCAVATION? YES NO

WERE BURIED FACILITIES EXPOSED BY HAND OR WITH NON-INVASIVE EQUIPMENT PRIOR TO EXCAVATION? YES NO

III. FACILITY INVOLVED (IF ANY)

TYPE OF FACILITY INVOLVED: NA OPERATOR OF FACILITY (IF KNOWN):

OPERATOR ADDRESS: PHONE NUMBER:

DEPTH OF COVER: PRESSURE: VOLTAGE: NUMBER OF CABLE PAIRS:

IV. MARKING

WERE FACILITIES MARKED? YES NO

WAS THE MARKING COMPLETE PRIOR TO THE START TIME ON THE TICKET? YES NO

DID EXCAVATOR PRE-MARK WITH WHITE PAINT? YES NO

WAS THE FACILITY MARKED ACCURATELY (WITHIN 18 INCHES)? YES NO

DID EXCAVATOR USE REASONABLE CARE TO MAINTAIN LOCATE MARKS FOR LIFE OF PROJECT? YES NO

HAVE YOU DISCUSSED THE PREVIOUS STATEMENTS WITH THE OTHER PARTY? YES NO

IS THERE AGREEMENT? YES NO

IF NO, PLEASE EXPLAIN: did not have a locate for diging started on 1-20-04

V. DAMAGE (IF ANY)

FATALITIES: NA INJURIES: NA LENGTH OF HOSPITALIZATION: NA

ESTIMATED PROPERTY DAMAGE (\$): NA NUMBER OF CUSTOMERS AFFECTED: NA

DAMAGED IN: PUBLIC PRIVATE (RIGHT-OF-WAY)

PHOTOS OF THE DAMAGED FACILITY? YES NO

ADDITIONAL INFORMATION:

PHOTOS OF THEM DIGING ON 1-20-04 TWO DAYS PRIOR TO START DATE

VI. PROBABLE VIOLATION

SPECIFIC STATUTE(S) OR RULE(S) THAT WAS VIOLATED:

SDCL 49-7A-5 NOTIFICATION OF PROPOSED EXCAVATION-Excavator did not allow for the 48 hours prior to

ADDRESS/LOCATION OF PROBABLE VIOLATION: HWY 71 AT THE NEW GOLF COURSE ADDITION TO HOT SPRINGS

DATE/TIME OF PROBABLE VIOLATION 1-20-04 AT 11AM

HAVE YOU DISCUSSED THIS PROBABLE VIOLATION WITH THE PARTY THE ACTION IS FILED AGAINST: YES NO

IF YES, NAME OF THE PARTY WITH WHOM YOU DISCUSSED THE PROBABLE VIOLATION:

DESCRIPTION OF PROBABLE VIOLATION:

On 1-12-04 I spoke with Olander contracting co (Mr. Barry Olander) I spoke with him on the issue of not calling in to the one call system prior to digging. at this time Mr. Olander told me that he did not have to call in a one call and that he already had a one call for the area in question. I then sighted that a locate is only good for 21 days and that his last request was on 4-25-03. He then wanted to end his conversation with me.

At this time I then went to our District Manager Jerry Schroeder and explained what we had going on. He then suggested that we contact the landowners and Mr. Olander to explain our stance on this problem. We did this on 1-12-04. once we had talked with both landowners we then contacted Mr. Olander stating that we wanted to work with him on this issue and that we had in the past. Jerry then explained that his crew was working at that time without a locate at the new Holiday Inn Express, but that we would gladly locate the facilities but that we wanted a locate for the digging that was taking place there. This was agreed on and we sent Lee Carr out to do the Locating for Olander Contracting. We found in the days after that Mr. Olander still never called in a locate. Also in Jerrys conversation with Mr. Olander he explained that when they move they also needed to call in a one call. Jerry then asked if he had a book and he said yes but Jerry said he would send him one just to be safe. Jerry sent the South Dakota One Call book by registered mail on 1-12-04 and Olander Contracting signed for the book on 1-14-04.

Then on 1-19-04 as I was driving down hwy 71 after work I noticed a track ho sitting in an area that we had not received a locate for. So the next day at 11am I wanted to go and check to see what was going on. At that time I noticed that Olander Construction was digging in the south east corner of the new golf course. I then went back to check the locates to see if they had called one in. They had but the start date was for 1-22-04. I then went out and took the pictures.

At around 11:30 Lee Carr called me to say that Olander Contracting had called him to ask if he could come out and see if there was any thing where they were at out at the golf course. Lee explained to one of Olanders hired men that he was busy with another locate at that time. Lee then directed him to our office in Hot Springs and told him to call me (scott). He told Lee that he had a locate and Lee told him he would check on the date when he got back but if he needed anything to call Scott at the office in Hot Springs. on 1-21-04 Olanders hired man called our office at about 8:10 am asking if someone was coming out to locate. I told him Lee would be right out to locate for him. This is still one day prior to his said start date.

COMMITTEE/BOARD ACTION

FOR PROBABLE CAUSE COMMITTEE / BOARD USE ONLY

REMARKS

RECOMMENDATION

FOR ENFORCEMENT COMMITTEE USE ONLY

NO VIOLATION EXISTS

VIOLATION OF SOUTH DAKOTA STATUTE(S) OR RULES(S):

WARNING LETTER: PROPOSED PENALTY (\$):

COMMENTS:

DISPOSITION

FOR BOARD USE ONLY

NO VIOLATION EXISTS

VIOLATION OF SOUTH DAKOTA STATUTE(S) OR RULES(S):

WARNING LETTER: PENALTY (\$):

COMMENTS:

OTHER:

HTSP PLANT

From: Automailer_DO_NOT_REPLY@1-call.com
Sent: Monday, January 19, 2004 11:55 AM
To: HotSpringsOneCall
Subject: OCS Ticket Transmission for GW1-ZD-040190075

South Dakota One Call SEQUENCE NUMBER 0001 CDC = GW1

Type: *** R O U T I N E *** Class: TRANSMIT

Transmit: 01/19/04 At: 1254 CST

Prepared: 19-JAN-04 Time: 1253 CST By: ISP

Ticket No.: 040190075

Operators Notified:
 GW1=/GOLDEN HOT SPRN/ BHP=/BLACK HILLS P&L/

Excavator Information:

Caller: ELROY REMMICK Phone: 701-232-6716

Excavator: OLANDER CONTRACTING CO
Address: 3155 44TH AVE NW
City: FARGO, ND 58107
Phone: 701-232-6716 Fax: 701-232-0144

Contact: BILL OLANDER Phone: 701-799-7607 MOBILE
Alt. Contact: ELROY REMICK Phone: 701-799-7606MOBILE

Location Information:

County: FALL RIVER City/Village: HOT SPRINGS City Limits?: U

Map Ref: 43242-103286 Grids: 20
Exc. Site Address: 0 UNKNOWN
Nearest Intersection: UNKNOWN
Type of Work : UG SEWER & WATER
Work Being Done For: GOLF COURSE & STEVE ZMONICK
Depth: 8' Explosives: N Tunnel/Bore: N
Start Date: 01/22/04 Time: 0001 CST Duration: 03 DAYS
Meeting Required: N Best Time to Contact: 0800 - 0800
Exc. Site (Marking Instr.): R.O.W.: Y TRSQ: 007S 05E 26-SE
 LOC THIS IS AT THE NEW GOLF COURSE PLEASE GO TO THE FRONT DESK &
 CALL ELROY FOR THE EXCACT LOCATES THIS IS ABOUT 1/2 FROM C & H
 BUILDINGS

Remarks:
 EXPIRES FEB 12 @ 00:01 CST

End Ticket

Is your RETURN ADDRESS completed on the reverse side?

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, 4a, and 4b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

I also wish to receive the following services (for an extra fee):

1. Addressee's Address

2. Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to:

Olander Contracting
 3155 44th Ave
 Fargo, ND 58107

4a. Article Number
 7000 1670 0001 22621

4b. Service Type

Registered Certified

Express Mail Insured

Return Receipt for Merchandise COD

7. Date of Delivery
 1-14-04

5. Received By: (Print Name)
 Dawn Nelson

8. Addressee's Address (Only if requested and fee is paid)

6. Signature: (Addressee or Agent)
 X Dawn Nelson

PS Form 3811, December 1994

102595-98-B-0229 Domestic Return Receipt

U.S. Postal Service
CERTIFIED MAIL RECEIPT
 (Domestic Mail Only. No Insurance Coverage Provided)

7000 1670 0001 22621 0000

FARGO ND 58107

Postage	\$ 10.83	0747 04 Postmark Here
Certified Fee	\$ 2.30	
Return Receipt Fee (Endorsement Required)	\$ 1.75	
Restricted Delivery Fee (Endorsement Required)	\$ 0.00	
Total Postage & Fees	\$ 14.88	

01/12/2004

Sent To
 Olander Contracting
 Street, Apt. No., or PO Box No.
 3155 44th Ave
 City, State, ZIP+4
 Fargo, ND 58107

0304251215132023406052

South Dakota One Call

SEQUENCE NUMBER 0001

CDC = GW1

Type: *** R O U T I N E

Class: TRANSMIT

Transmit: 04/25/03

At: 1107 CDT

Prepared: 25-APR-03

Time: 1107 CDT By: MIK

Ticket No.: 031150269

Operators Notified:

BHP=/BLACK HILLS P&L/ GW1=/GOLDEN HOT SPRN/ HOT=/HOT SPRNGS CITY/
SDC=/MCC SPEARFISH /

Excavator Information:

Caller: ELROY REMMICK Phone: 701-232-6716

Excavator: OLANDER CONTRACTING CO

Address: 3155 44TH AVE NW

City: FARGO, ND 58107

Phone: 701-232-6716

Fax: 701-232-0144

Contact: BILL OLANDER

Phone: 701-799-7607 MOBILE

Alt. Contact: ELROY REMICK

Phone: 701-799-7606MOBILE

Location Information:

County: FALL RIVER

City/Village: HOT SPRINGS

City Limits?: N

Map Ref: 43252-103296

Grids: 20

Exc. Site Address: 0 HWY 18 TRUCK BYPASS

Nearest Intersection: 20TH ST

Type of Work : INSTALL UG SWR & WTR

Work Being Done For: CALVIN LORENZ

Depth: 6-13FT

Explosives: N

Tunnel/Bore:

N

Start Date: 04/29/03

Time: 1056 CDT

Duration: 99

DAYS

Meeting Required: N

Best Time to Contact: 0700 - 0700

Exc. Site (Marking Instr.): R.O.W.: N TRSQ: 007S 05E 22-NE-SE

FROM THE INTER GO WEST 1/2MI ON HWY 18 BYPASS, START MARKING HERE
GOING SOUTH FOR 1/2MI..

Remarks:

EXPIRATION DATE 20-MAY-03

ALSO SEC 23 NW & SW

ANY QUESTIONS CALL ELROY ON HIS CELL PHONE..

End Ticket


□□

Jan. 20, 2004

Elroy, from Blunder Contractors, called me on my cell phone at approximately 11:00 AM on this date. He was asking about locating on Highway 71. I told him that I was east of Big Bend Gap and he would have to call the office and talk to Scott Harbless.

At that time he told me that he had a 'one-call cable locate' called in. I told him that there would be a due date on that locate and I would check on that when I returned to the office. If he needed more than that he should call Scott at the office.

Jan Carr



Mail completed form to:

**PUBLIC UTILITIES COMMISSION
500 EAST CAPITOL AVENUE
PIERRE, SD 57501
ATTN: SOUTH DAKOTA ONE CALL BOARD**

COMPLAINT

COMPLETE INFORMATION IS REQUIRED – ADDITIONAL PAGES MAY BE USED IF REQUIRED

ALLEGATION OF PROBABLE VIOLATION(S) OF SOUTH DAKOTA ONE CALL LAWS

I. ACTION REQUESTED BY:

COMPLAINT FILED BY INDIVIDUAL OR BUSINESS* PERSON FILING COMPLAINT: Scott Harkless

COMPANY: Golden West Telecommunications Coop, Inc. ADDRESS: 1510 National Avenue, Hot Springs, SD 57747

PHONE NUMBER: 605-745-3103

SIGNATURE: Scott W. Harkless DATE: 1/20/04 EMAIL ADDRESS: scottharkless@goldenwest.com

*If the complaint is files on behalf of a Company, the person signing this form should have the proper authority to file the complaint.

II. ACTION REQUESTED AGAINST:

NAME OF EXCAVATOR/FACILITY OPERATOR: Olander Contracting Company PHONE NUMBER: 701-232-6716

ADDRESS: 3155 44th Ave. NW, Fargo, ND 58107

WAS A LOCATE REQUESTED FROM SD ONE CALL? YES NO LOCATE TICKET #: 040190075

START DATE ON TICKET: 1/22/04 DID EXCAVATOR WAIT UNTIL THE START DATE/TIME ON THE TICKET BEFORE STARTING EXCAVATION? YES NO NA WERE BURIED FACILITIES EXPOSED BY HAND OR WITH NON-INVASIVE EQUIPMENT PRIOR TO EXCAVATION? YES NO NA

III. FACILITY INVOLVED (IF ANY)

TYPE OF FACILITY INVOLVED:

OPERATOR OF FACILITY:

OPERATOR ADDRESS:

PHONE NUMBER:

DEPTH OF COVER:

PRESSURE:

VOLTAGE:

NUMBER OF CABLE PAIRS:

IV. MARKING

WERE FACILITIES MARKED? YES NO NA

WAS THE MARKING COMPLETE PRIOR TO THE START TIME ON THE TICKET? YES NO NA

DID EXCAVATOR PRE-MARK WITH WHITE PAINT? YES NO NA WAS THE FACILITY MARKED ACCURATELY (WITHIN 18 INCHES)? YES NO NA DID EXCAVATOR USE REASONABLE CARE TO MAINTAIN LOCATE MARKS FOR LIFE OF PROJECT? YES NO NA HAVE YOU DISCUSSED THE PREVIOUS STATEMENTS WITH THE OTHER PARTY? YES NO IS THERE AGREEMENT? YES NO
IF NO, PLEASE EXPLAIN: Olander Contracting Company did not have a ticket for digging that started on 1-20-04 or earlier

V. DAMAGE (IF ANY)

FATALITIES: INJURIES: LENGTH OF HOSPITALIZATION:
ESTIMATED PROPERTY DAMAGE (\$): NUMBER OF CUSTOMERS AFFECTED:
DAMAGED IN: PUBLIC PRIVATE (RIGHT-OF-WAY)
PHOTOS OF THE DAMAGED FACILITY? YES NO
ADDITIONAL INFORMATION:

VI. PROBABLE VIOLATION

SPECIFIC STATUTE(S) OR RULE(S) THAT WERE VIOLATED:

A) SDCL 49-7A-5 Notification of proposed excavation. – Olander Contracting Company did not allow the 48 hour interval prior to commencing excavation. Based on information provided in the complaint, Golden West Telecommunications request the Board Panel to consider applying SDCL 49-7A-19 Penalties for intentional violation as related to this violation.

B) ARSD 20:25:03:04 Information required when initiating a routine locate request. Olander Contracting Company did not provide information required to allow for the site to be marked in compliance with the statute

ADDRESS/LOCATION OF PROBABLE VIOLATION: HWY 71 at the New Golf Course addition.

DATE/TIME OF PROBABLE VIOLATION: 1-20-04 at approximately 11:00 AM


HAVE YOU DISCUSSED THIS PROBABLE VIOLATION WITH THE PARTY THE ACTION IS FILED AGAINST:
YES NO Golden West has not discussed this specific violation with Olander Contracting Company but has had previous discussion with them regarding compliance with South Dakota One Call statutes?

IF YES, NAME OF THE PARTY WITH WHOM YOU DISCUSSED THE PROBABLE VIOLATION:

DESCRIPTION OF PROBABLE VIOLATION:

On 1-12-04 I spoke with Olander Contracting Company (Mr. Barry Olander) on the issue of providing notification to the South Dakota One Call System prior to digging. During this conversation, Mr. Olander told me that he did not have to provide notification to the South Dakota One Call System and that he already had a ticket for the excavation area in question. I advised him that the last ticket we had was 4-25-03 and that ticket expires after twenty-one days. At this point, he did not want to discuss the issue further.

Following this conversation, I went to our District Manager Jerry Schroeder and explained the situation. He suggested we contact the landowners and Mr. Olander to explain Golden West Telecommunications position on this problem. Following completion of the discussion with both landowners on January 12th, we contacted Mr. Olander stating our desire to work with him on this issue. Jerry then explained that his crew was currently working at the new Holiday Inn Express without providing notification to the South Dakota One Call System as required by statute, further discussion resulted in an agreement that we would locate the facilities at the Holiday Inn Express site but that Golden West Telecommunications would require a locate request be made for the digging that was

taking place there. Both parties agreed on this course of action and Golden West Telecommunications dispatched Lee Carr out to the Holiday Inn Express site to complete the marking of facilities for Olander Contracting Company. We subsequently reviewed the tickets received from the South Dakota One Call System and discovered that Mr. Olander had not notified the South Dakota One Call System of his excavation activity at the Holiday Inn Express site as agreed to in previous conversations. During the conversation regarding the Holiday Inn Express site, Jerry explained to Mr. Olander that when they changed excavation sites South Dakota statute required they provide notification to the South Dakota One Call System. Jerry then asked if he had a copy of the Excavators Manual and he said yes but Jerry said he would send him one just to be safe. Jerry sent the Excavators Manual by registered mail on 1-12-04 and Olander Contracting Company signed that they received the manual on 1-14-04. On 1-19-04 as I was driving down Hwy 71, I noticed a track ho sitting in an area that we had not located. The next day at approximately 11AM, I returned to the site to determine if excavation activity was occurring. At that time I noticed that Olander Contracting Company was digging in the south east corner of the new golf course. I then returned to our office to verify the locate tickets received by Golden West Telecommunications to determine if Olander Contracting Company had provided notification to the South Dakota One Call System of this excavation activity. I did find ticket number 040190075 which had a start date was for 1-22-04 (copy of ticket attached). I then returned to the excavation site and took the pictures of the excavation activity (copies attached). I certify that the attached pictures were taken by me, Scott Harkless on January 20, 2004 

Following this activity, Lee Carr (Golden West technician) contacted me to say that Olander Contracting had called him to ask if he could come out and see if there were any facilities where they were digging at the new golf course. Lee explained to an employee of Olander Contracting Company that he was busy with another locate at that time. Lee advised the employee to contact me (Scott) at the Hot Springs office. The employee advised Lee that he had a locate and Lee told him he would check on the date when he got back but if he needed anything to call Scott at the office in Hot Springs. On 1-21-04 shortly after 8:00 AM an employee of Olander Contracting again called our office asking if someone was coming out to locate. I told him Lee would be right out to locate for him. This was still one day prior to his said start date.

It is obvious from these events that Olander Contracting Company clearly knows that underground facilities are in the vicinity of the digging and also knows that they have a requirement to advise the South Dakota One Call System. It is also obvious that Olander Contracting Company does not have the desire to follow the statutory requirements of the South Dakota One Call System.

The pattern of disregard for the South Dakota One Call System is also evident in the lack of information provided in locate request 04090075. On this locate request, Olander Contracting Company did not provide information required in ARSD 20:25:03:04 (7) which was readily available such as specific address; intersecting street; and the legal description was not accurate. On this locate request Olander Contracting Company also failed to provide information required in ARSD 20:25:03:04 (8) the specific marking instructions. A copy of this locate request is attached and a copy of the recorded telephone call is available should any party desire to review the information provided by Olander Contracting Company during this call.

From our discussions with Olander Contracting Company, it is apparent that there currently is no desire to comply with the requirements of SDCL 49-7A and ARSD 20:25. Golden West Telecommunications has made a concerted effort to assist Olander Contracting Company in understanding the requirements of the statute but has been unsuccessful in obtaining a reasonable response.

HTSP PLANT

From: Automailer_DO_NOT_REPLY@1-call.com
Sent: Monday, January 19, 2004 11:55 AM
To: HotSpringsOneCall
Subject: OCS Ticket Transmission for GW1-ZD-040190075

South Dakota One Call SEQUENCE NUMBER 0001 CDC = GW1
Type: *** R O U T I N E *** Class: TRANSMIT
Transmit: 01/19/04 At: 1254 CST
Prepared: 19-JAN-04 Time: 1253 CST By: ISP
Ticket No.: 040190075

Operators Notified:
 GW1-/GOLDEN HOT SPRN/ BHP=/BLACK HILLS P&L/

Excavator Information:

Caller: ELROY REMMICK Phone: 701-232-6716

Excavator: OLANDER CONTRACTING CO
Address: 3155 44TH AVE NW
City: FARGO, ND 58107
Phone: 701-232-6716 Fax: 701-232-0144

Contact: BILL OLANDER Phone: 701-799-7607 MOBILE
Alt. Contact: ELROY REMICK Phone: 701-799-7606MOBILE

Location Information:

County: FALL RIVER **City/Village:** HOT SPRINGS **City Limits?:** U

Map Ref: 43242-103286 **Grids:** 20
Exc. Site Address: 0 UNKNOWN
Nearest Intersection: UNKNOWN
Type of Work : UG SEWER & WATER
Work Being Done For: GOLF COURSE & STEVE ZMONICK
Depth: 8' **Explosives:** N **Tunnel/Bore:** N
Start Date: 01/22/04 **Time:** 0001 CST **Duration:** 03 DAYS
Meeting Required: N **Best Time to Contact:** 0800 - 0800
Exc. Site (Marking Instr.): R.O.W.: Y TRSQ: 0078 05E 26-SE
 LOC THIS IS AT THE NEW GOLF COURSE PLEASE GO TO THE FRONT DESK &
 CALL ELROY FOR THE EXCACT LOCATES THIS IS ABOUT 1/2 FROM C & H
 BUILDINGS

Remarks:

EXPIRES FEB 12 @ 00:01 CST

End Ticket

0304251215132023406052

South Dakota One Call

SEQUENCE NUMBER 0001 CDC = GW1

Type: *** R O U T I N E

*** Class: TRANSMIT

Transmit: 04/25/03

At: 1107 CDT

Prepared: 25-APR-03

Time: 1107 CDT By: MIK

Ticket No.: 031150269

Operators Notified:

BHP=/BLACK HILLS P&L/ GW1=/GOLDEN HOT SPRN/ HOT=/HOT SPRNGS CITY/
SDC=/MCC SPEARFISH /

Excavator Information:

Caller: ELROY REMMICK Phone: 701-232-6716

Excavator: OLANDER CONTRACTING CO

Address: 3155 44TH AVE NW

City: FARGO, ND 58107

Phone: 701-232-6716

Fax: 701-232-0144

Contact: BILL OLANDER

Phone: 701-799-7607 MOBILE

Alt. Contact: ELROY REMICK

Phone: 701-799-7606MOBILE

Location Information:

County: FALL RIVER City/Village: HOT SPRINGS City Limits?: N

Map Ref: 43252-103296

Grids: 20

Exc. Site Address: 0 HWY 18 TRUCK BYPASS

Nearest Intersection: 20TH ST

Type of Work : INSTALL UG SWR & WTR

Work Being Done For: CALVIN LORENZ

Depth: 6-13FT

Explosives: N

Tunnel/Bore:

N

Start Date: 04/29/03

Time: 1056 CDT

Duration: 99

DAYS

Meeting Required: N

Best Time to Contact: 0700 - 0700

Exc. Site (Marking Instr.): R.O.W.: N TRSQ: 007S 05E 22-NE-SE

FROM THE INTER GO WEST 1/2MI ON HWY 18 BYPASS, START MARKING HERE
GOING SOUTH FOR 1/2MI..

Remarks:

EXPIRATION DATE 20-MAY-03

ALSO SEC 23 NW & SW

ANY QUESTIONS CALL ELROY ON HIS CELL PHONE..

End Ticket

□□

Is your RETURN ADDRESS completed on the reverse side?

SENDER:

- Complete items 1 and/or 2 for additional services.
- Complete items 3, 4a, and 4b.
- Print your name and address on the reverse of this form so that we can return this card to you.
- Attach this form to the front of the mailpiece, or on the back if space does not permit.
- Write "Return Receipt Requested" on the mailpiece below the article number.
- The Return Receipt will show to whom the article was delivered and the date delivered.

I also wish to receive the following services (for an extra fee):

- 1. Addressee's Address
- 2. Restricted Delivery

Consult postmaster for fee.

3. Article Addressed to:
 Olander Contracting
 3155 44th Ave
 Fargo, ND 58107

4a. Article Number
 7000 1670 0001 2262/4

4b. Service Type
 Registered Certified
 Express Mail Insured
 Return Receipt for Merchandise COD

7. Date of Delivery
 1-14-04

5. Received By: (Print Name)
 Dawn Nelsen

8. Addressee's Address (Only if requested and fee is paid)

6. Signature: (Addressee or Agent)
 X Dawn Nelsen

PS Form 3811, December 1994

102595-98-B-0229 Domestic Return Receipt

7000 1670 0001 2262 1A09

U.S. Postal Service
CERTIFIED MAIL RECEIPT
 (Domestic Mail Only - No Insurance Coverage Provided)

FARGO ND 58107

Postage	\$ 01.83	0747 04 Postmark Here
Certified Fee	\$2.30	
Return Receipt Fee (Endorsement Required)	\$1.75	
Restricted Delivery Fee (Endorsement Required)	\$0.00	
Total Postage & Fees	\$4.88	

01/12/2004

Sent To
 Olander Contracting
 Street, Apt. No., or PO Box No.
 3155 44th Ave
 City, State, ZIP+4
 Fargo, ND 58107

PS Form 3811, Dec 2004 See Reverse for Instructions

Jan. 20, 2004

Elroy, from Clearwater Contractors, called me on my cell phone at approximately 11 o'clock on this date. He was asking about locating on Highway 71. I told him that I was east of Buffalo Gap and he would have to call the office and talk to Scott Haskless.

At that time he told me that he had a 'one-call cable locate' called in. I told him that there would be a due date on that locate and I would check on that when I returned to the office. If he needed more than that he should call Scott at the office.

Jan Can