

Incident Report

Incident Classification

Classifying the incident is described in SIP-ADM-13.01.

- Hazard Near Miss Minor (Less Than \$25K) Significant (\$25K - \$500K) Major (More Than \$500K)

General Information

***Incident Name**

03/18/2021 One
Call/Encroachment MPC - Rapid
City SD

***Incident Start Date**

2021-03-18

***Incident Start Time**

16:03:00

Incident End Date

2021-03-19

Incident End Time

15:30:00

Incident Report Date

2021-03-19

Incident Report Time

13:54:00

Prepared By:

Johring, Mark

***Operating Company**

Magellan Midstream Partners

***Incident Responsible
Supervisor**

Anderson, Ryan

***Location of Incident (where incident occurred)**

MPC - Rapid City SD

***Incident Address**

3225 Eglin St

***Incident City**

Rapid City

***Incident State**

South Dakota

***Incident Zip Code**

57703

***Area**

Rocky Mountain North

***District**

Central

***Employee/Asset Location (employee home location)**

MPC - Rapid City SD

***Did incident involve a joint venture (JV)?**

No

***PSM/RMP Asset**

Yes No

***MP (Mitigation Plan) Asset**

Yes No

***OQ Task Involved**

Yes No

Incident Description

***Who was involved in the incident?**

- | | | | |
|--|---|--|---|
| <input type="checkbox"/> Magellan
Asset Integrity
(Field)
Employee(s) | <input type="checkbox"/> Magellan
Operations
Control
Employee(s) | <input type="checkbox"/> Magellan
Operations
Employee(s) | <input type="checkbox"/> Magellan
Tower
Employee(s) |
| <input checked="" type="checkbox"/> Non-Magellan
Individual | | | |

Individual Type Contractor

Other Individual Type:

Name: Derek Quinn
Address: 14639 Wagner Ln.
 Rapid City SD
 57701

Telephone: (605) 787-6500
Email: julie@quinnconstruction.org

Company: Quinn
 Construction, Inc

Access Suspended or Terminated

***Incident Description:**

At approximately 16:03 03/182021, Magellan's contracted patrol pilot, on his weekly pipeline patrol, reported heavy equipment activity along Magellan Midstream Partners pipeline right of way, at approximately milepost 187.5, north of Homestead Street in Rapid City, SD.

***Immediate actions taken:**

Patrol pilot reported the sighting to Magellan employee at approximately 17:25 on 03/18/2021. Magellan employee dispatched to the location and found equipment parked near the line. Equipment had decals indicating that the equipment belonged to Quinn Construction Inc. Magellan Employee inspected the site and took a number of photographs. No activity appeared to have taken place within 15 feet of the pipeline at the closest point. Upon arriving at Magellan's office, Magellan employee verified that there was no One Call request in Magellan's system. Magellan employee then called Quinn Construction to visit about the excavation activity. Derek Quinn returned the call and noted that he had checked and there was no current One Call in place. Mr. Quinn indicated that he had stopped all activity on the site until he had a valid One Call in place. Mr. Quinn was very helpful and apologetic about the incident and proceeded to place a One Call request.

Current Status of Incident

Resolved

Describe on how the incident was resolved (be specific):

Mr. Quinn immediately halted any excavation activity on the site in question. Mr. Quinn then submitted a One Call request, SD2107867254. Mr. Quinn is aware of the presence of the pipeline in the area. The lack of a One Call was an oversight, probably a failure to renew a ticket. Estimated cost is just the cost of an after hours call out for Magellan employee.

Estimated Cost

\$300

Incident Details

Incident Type

- | | | | |
|---|--|--|---|
| <input type="checkbox"/> Abnormal Operations (AO) | <input type="checkbox"/> Injury/Illness/Exposure | <input type="checkbox"/> Motor Vehicle | <input checked="" type="checkbox"/> One Call/Encroachment |
| <input type="checkbox"/> Product Quality | <input type="checkbox"/> Property Damage | <input type="checkbox"/> Release | <input type="checkbox"/> Security |
| <input type="checkbox"/> Other | | | |

***Activity at Time of Incident**

- | | |
|--|---|
| <input type="checkbox"/> Cell Phone In Use | <input type="checkbox"/> Construction |
| <input type="checkbox"/> Driving | <input type="checkbox"/> Emergency Response |
| <input checked="" type="checkbox"/> Excavation | <input type="checkbox"/> Lifting |
| <input type="checkbox"/> Loading/Unloading | <input type="checkbox"/> Maintenance |
| <input type="checkbox"/> Material Handling | <input type="checkbox"/> Normal Operations |
| <input type="checkbox"/> Office Work | <input type="checkbox"/> Remediation |
| <input type="checkbox"/> Repair | <input type="checkbox"/> Shutdown |
| <input type="checkbox"/> Start-Up | <input type="checkbox"/> Other |

***Conditions**

- | | |
|-------------------------------|---|
| <input type="checkbox"/> Cold | <input type="checkbox"/> Employee <1 Year |
|-------------------------------|---|

- Heat
- Late in Shift
- Normal
- Rain
- Tight Space

- Ice/Snow
- Night/Low Light
- Overtime
- Shift Change
- Other

0 Notes

One Call/Encroachment Violation Information

Location of Incident

Address 0 Copperfield Drive
City Rapid City
State South Dakota
Zip 57701
Nearest Intersection Copperfield Drive and Homestead Street
Latitude 44.0799
Longitude -103.1615

Affected Facility Information

Was Pipe or Coating Damaged?

Yes No

Was the facility part of a joint trench? *(A joint trench contains different utilities together in one trench.)*

No

Did this event involve a Cross Bore? *(A cross bore occurs when one underground facility is bored through another underground facility.)*

Yes No

Distance between pipeline and excavation at closest point

15 ft. 0 in.

Measured Depth of Excavation

1 ft. 0 in.

Measured Pipeline depth of cover from existing/undisturbed ground

5 ft. 0 in.

Incident Information

Right-of-Way where event occurred

Pipeline

Type of Excavator

Developer

Type of Excavation Equipment

Grader/Scraper

Type of Work Performed

Site Development

Notification and Locating Information

Was the One-Call Center notified?

Yes

No

Was work area white-lined?

No

Root Cause

Notification Issue

Subcause

No notification made to One Call Center/
811

Retention: 5 Years