



INCIDENT INVESTIGATION #205087



7916 Duke Parkway, Spearfish, SD

LOCATION DETAILS

Event Date: 03/18/2021 09:30 AM America/Denver

Right-of-Way: Private Land

AFFECTED FACILITY

Near Miss: No

Type of Operation Affected: Gas

Line Size and Type: 3/4" Plastic

Facility part of joint trench: Yes

Asphalt or concrete removed: No

Damage Surface Type and Depth: Dirt 18" - 36"

Arrival Date and Time: 03/18/2021 01:09 PM America/Denver



Distance from Ped to Ped: 0ft

Dimensions of Asphalt or Concrete Removed:

Repairs Taking Place Upon Arrival? Yes

Who Performed Repairs: Both

Contractor Representative: Jimmy Dowden

Contractor Representative Phone Number: (530) 816-0028

Personnel On Site: Jimmy Dowden Contractor / Bruce Sprynczynatyk from MDU

Vehicles/Equipment Being Used For Repairs: Hand tools

Guards or Barricades On Site: No

Facilities Replaced or Repaired: Replaced

Replacement Type: Permanant

Occurred During: Business Hours

Time Occurred: 9:30 AM America/Denver

DAMAGER

Company Name: Dowden Creative Construction

Contact: Jimmy Dowden

Contact Phone: (530) 816-0028

Type of Work: Utilities trench

Damage Responder: Jessica, Myers

UTILITY INFORMATION

Utility Company Name: Montana Dakota Utilities

Utility Contact Name: Bruce Sprynczynatyk

Utility Contact Phone: (605) 645-1541

Utility Representative: Dale

Utility Rep Tech#:

Utility Rep. Present on Arrival: Yes

EXCAVATION INFORMATION

Excavator Type: Contractor

Excavation Equipment: Backhoe/Trackhoe

Work Performed: Bldg. Construction

Excavator downtime? Yes

Downtime hours: 2

Downtime cost: No

NOTIFICATION AND LOCATING

One Call Center notified: Yes

Locator Type: Contract Locator

Work area white-lined: No

Ticket Number: 2105460998

Date Located: 02/24/2021 12:07 PM America/Denver

Located By: Jessica Myers

INTERRUPTION AND RESTORATION

Event cause Interruption: Yes

Interruption hours: 2

Customers Affected (approx.): 1

ROOT CAUSE

Root Cause: Marks faded, lost or not maintained

COMMENTS

Assessment Comments: Located this ticket 2-24-21. Contractor dug on this ticket after snow melted, and then it snowed again. Damage took place between 9:30 and 10 am on 3-18-21. MDU did not get notified until 12:00. ELM did not get notified until 1:00 pm. Gas service at 7916 was hit digging trench for lot 12. With a Mini excavator. 911, 811 and MDU were all notified. Dale with MDU arrived to pinch off and fix line.

INCIDENT AND SURVEY COMPARISON PHOTOS

SURVEY PHOTO



Ticket: 2105460998.0 Timestamp:2/24/2021 11:19:08 AM

Date: 02/24/2021 12:19 PM
America/Denver

Latitude: 44.485556

Longitude: -103.730833

Heading: 214 degrees

INCIDENT COMPARISON PHOTO



Date: 03/18/2021 01:23 PM
America/Denver

Latitude: 44.484729

Longitude: -103.731195

Heading: 215 degrees

SURVEY PHOTO



Ticket: 2105460998.0 Timestamp:2/24/2021 11:19:08 AM

Date: 02/24/2021 12:19 PM
America/Denver

Latitude: 44.485556

Longitude: -103.730833

Heading: 214 degrees

INCIDENT COMPARISON PHOTO



Date: 03/18/2021 01:24 PM
America/Denver

Latitude: 44.484729

Longitude: -103.731195

Heading: 220 degrees

SURVEY PHOTO



Ticket: 2105460998.0 Timestamp:2/24/2021 11:19:10 AM

Date: 02/24/2021 12:19 PM
America/Denver

Latitude: 44.485556

Longitude: -103.730833

Heading: 206 degrees

INCIDENT COMPARISON PHOTO



Date: 03/18/2021 01:26 PM
America/Denver

Latitude: 44.484730

Longitude: -103.731195

Heading: 203 degrees

SURVEY PHOTO



Ticket: 2105460998.0 Timestamp:2/24/2021 11:19:10 AM

Date: 02/24/2021 12:19 PM
America/Denver

Latitude: 44.485556

Longitude: -103.730833

Heading: 206 degrees

INCIDENT COMPARISON PHOTO



Date: 03/18/2021 01:27 PM
America/Denver

Latitude: 44.484730

Longitude: -103.731195

Heading: 223 degrees

NEW INCIDENT PHOTOS



Date: 03/18/2021 01:26 PM
America/Denver

Latitude: 44.484730

Longitude: -103.731195

Heading: 268 degrees



Date: 03/18/2021 01:26 PM
America/Denver

Latitude: 44.484730

Longitude: -103.731195

Heading: 162 degrees