

TICKET 2215206544



Ticket Number: 2215206544 Old Ticket:
Source: Voice Type: Damage
Date: 6/1/2022 9:57 AM
Update By: 6/17/2022 12:00 PM Expires On: 6/22/2022 12:00 PM

RESPONSE STATUS AS OF FRIDAY, JUNE 24, 2022 10:13 AM

| STATUS | CODE | NAME | FACILITIES |
|--------|------|------|------------|
|--------|------|------|------------|

COMPANY INFORMATION

Brooks Construction Services Inc.
27081 SUNDOWNER AVE
SIOUX FALLS , SD 57106

Phone: (605) 368-5447

Fax:

Type: Excavator

| | <u>Name</u> | <u>Phone</u> | <u>Email</u> |
|--------------|--------------|----------------|-----------------------------------|
| Caller | LEXIE KRAMER | (605) 368-5447 | ap@brooksconstructionservices.com |
| Contact | JON SMIDT | (605) 521-0624 | ap@brooksconstructionservices.com |
| Alt Phone | | (605) 368-5447 | |

WORK INFORMATION

| | | | |
|-----------------|-----------------------------|-----------------|---------------------|
| State: | SD | Work Date: | 6/1/2022 12:00 PM |
| County: | MINNEHAHA | Done For: | Brooks Construction |
| Place: | RENNER CORNER | Duration: | 1 week |
| Street: | 25757 475th Ave | Explosives: | False |
| Intersection: | 258th ave | Right of Way: | False |
| Nature of Work: | DAMAGE- HIT UNKNOWN LINE | Tunnel/Bore: | False |
| Meet Requested: | False | Meet Date/Time: | |
| TRSQ: | | Depth: | 48" |

DRIVING DIRECTIONS

REMARKS

**DAMAGE-2214399537 HIT UNKNOWN LINE- CREW ONSITE, CUSTOMERS W/ SERVICE, LINE IS VISIBLE, CUSTOMER SERVICE IS UNKNOWN, HIT UNKNOWN LINE, HIT MY BROOKS CONSTRUCITON, HIT W/ MINI EXCAVATOR **
ON N SIDE OF PROPERTY LOCATE AT HIT LINE

Utilities must respond within 2 hours M-F and within 4 hours after working hours.

MEMBERS

| CODE | NAME |
|------|----------------------------|
| UW1 | CTLQL-CenturyLink |
| SFA | City Of Sioux Falls |
| CG1 | Crooks Municipal Gas *HP* |
| CMG | Crooks Municipal Utilities |

| CODE | NAME |
|------|-----------------------------|
| SFC | Midcontinent Communications |
| MCW | Minnehaha Community Water |
| REN | Renner Sanitary |
| N04 | Xcel Energy |

HP – A high profile facility is in the area and a meet may be required. The operator may also require to be present when excavating. Please refer to Administrative Rule #20:25:03:10.02.