



INCIDENT INVESTIGATION #191870



811 Pine St, Whitewood , SD

LOCATION DETAILS

Event Date: 05/08/2020 01:43 PM America/Denver

Right-of-Way: Private Land

AFFECTED FACILITY

Near Miss: No

Type of Operation Affected: Gas

Line Size and Type: 1 1/4" Steel

Facility part of joint trench: No

Asphalt or concrete removed: No

Damage Surface Type and Depth: Dirt < 18"

Arrival Date and Time: 05/12/2020 11:52 AM America/Denver



Distance from Ped to Ped: 0ft

Dimensions of Asphalt or Concrete Removed:

Repairs Taking Place Upon Arrival? No

Who Performed Repairs: Utility Company

Contractor Representative: Shawn Karol

Contractor Representative Phone Number: (605) 641-7026

Personnel On Site: 1tech

Vehicles/Equipment Being Used For Repairs: 1 truck

Guards or Barricades On Site: No

Facilities Replaced or Repaired:

Replacement Type:

Occurred During: Business Hours

Time Occurred: 1:43 PM America/Denver

DAMAGER

Company Name: KR Builders

Contact: Shawn Karol

Contact Phone: (605) 641-7026

Type of Work: Unknown excavation

Damage Responder: Russ, Simkins

UTILITY INFORMATION

Utility Company Name: Montana Dakota Utilities

Utility Contact Name: Bruce

Utility Contact Phone: (605) 645-1541

Utility Representative: Bruce

Utility Rep Tech#:

Utility Rep. Present on Arrival: Yes

EXCAVATION INFORMATION

Excavator Type: Contractor

Excavation Equipment: Backhoe/Trackhoe

Work Performed: Unknown/Other

Excavator downtime? No

Downtime hours: No

Downtime cost: No

NOTIFICATION AND LOCATING

One Call Center notified: No

Locator Type:

Work area white-lined: No

Ticket Number:

Date Located:

Located By: No locate requested

INTERRUPTION AND RESTORATION

Event cause Interruption: No

Interruption hours:

Customers Affected (approx.):

ROOT CAUSE

Damage within described dig area: No

Damage within legal time of request limit: No

Marks destroyed by construction: No

Marks destroyed by weather: No

Whiskers or flags used: No

Offsets were used on hard surfaces: No

Line was on prints: Yes

At Fault: Unknown/Other

Documentation Issue: No

Documentation Issue Comments:

Tolerance Zone: No

Marking Standards: No

Marking Standards Comments:

Locate Requested: No

Damage with Tolerance Zone: No


No Locates on Facility: Yes

Damage Exposed Facility: No

COMMENTS

Assessment Comments: On May 8 the contractor doing unknown excavation without a locate request pulled up and bent a steel gas service with a backhoe gas was not blowing 811 was notified MDU said that they were not going to replace the line or fix it because it is going to be abandoned the house is being demolished.

NEW INCIDENT PHOTOS



Date: 05/12/2020 11:52 AM
America/Denver

Latitude: 44.520363

Longitude: -103.891028

Heading: 166 degrees



Date: 05/12/2020 11:52 AM
America/Denver

Latitude: 44.520376

Longitude: -103.891050

Heading: 53 degrees