

Mail completed form to:

PUBLIC UTILITIES COMMISSION
500 EAST CAPITOL AVENUE
PIERRE, SD 57501
ATTN: SOUTH DAKOTA ONE CALL BOARD

RECEIVED

JUN 19 2003

SOUTH DAKOTA PUBLIC
UTILITIES COMMISSION

COMPLAINT

COMPLETE INFORMATION IS REQUIRED - ADDITIONAL PAGES MAY BE USED IF REQUIRED

ALLEGATION OF PROBABLE VIOLATION(S) OF SOUTH DAKOTA ONE CALL LAWS

I. ACTION REQUESTED BY:

COMPLAINT FILED BY INDIVIDUAL OR BUSINESS* PERSON FILING COMPLAINT (Please print): _____

COMPANY (If applicable) Midcontinent Comm ADDRESS 3507 S. Duluth PHONE NUMBER _____

SIGNATURE OF COMPLAINANT: [Signature] DATE: 6/16/03 EMAIL ADDRESS: _____

*If the complaint is filed on behalf of a Company, the person signing this form should have the proper authority to file the complaint.

II. ACTION REQUESTED AGAINST:

NAME OF EXCAVATOR/FACILITY OPERATOR: Gleason Tree Co. PHONE NUMBER: (605) 368-2678

ADDRESS: 27226 471st Ave. Harrisburg S.D. 57035

WAS A LOCATE REQUESTED FROM SD ONE CALL? YES NO LOCATE TICKET #: 03/630327 START DATE ON TICKET: 6-16-03

DID EXCAVATOR WAIT UNTIL THE START DATE/TIME ON THE TICKET BEFORE COMMENCING EXCAVATION? YES NO

WERE BURIED FACILITIES EXPOSED BY HAND OR WITH NON-INVASIVE EQUIPMENT PRIOR TO EXCAVATION? YES NO

III. FACILITY INVOLVED (IF ANY)

TYPE OF FACILITY INVOLVED: Communications OPERATOR OF FACILITY (IF KNOWN): Midcontinent Comm.

OPERATOR ADDRESS: 3507 S. Duluth Ave. S.F. SD. 57004 PHONE NUMBER: _____

DEPTH OF COVER: 28" PRESSURE: _____ VOLTAGE: _____ NUMBER OF CABLE PAIRS: _____

IV. MARKING

WERE FACILITIES MARKED? YES NO WAS THE MARKING COMPLETE PRIOR TO THE START TIME ON THE TICKET? YES NO NA

DID EXCAVATOR PRE-MARK WITH WHITE PAINT? YES NO

WAS THE FACILITY MARKED ACCURATELY (WITHIN 18 INCHES)? YES NO NA

DID EXCAVATOR USE REASONABLE CARE TO MAINTAIN LOCATE MARKS FOR LIFE OF PROJECT? YES NO NA

HAVE YOU DISCUSSED THE PREVIOUS STATEMENTS WITH THE OTHER PARTY? YES NO

IS THERE AGREEMENT? YES NO IF NO, PLEASE EXPLAIN: _____

V. DAMAGE (IF ANY)

FATALITIES: _____ INJURIES: _____ LENGTH OF HOSPITALIZATION: _____

Mail completed form to:

PUBLIC UTILITIES COMMISSION
500 EAST CAPITOL AVENUE
PIERRE, SD 57501
ATTN: SOUTH DAKOTA ONE CALL BOARD

COMPLAINT

COMPLETE INFORMATION IS REQUIRED – ADDITIONAL PAGES MAY BE USED IF REQUIRED

ALLEGATION OF PROBABLE VIOLATION(S) OF SOUTH DAKOTA ONE CALL LAWS

I. ACTION REQUESTED BY:

COMPLAINT FILED BY INDIVIDUAL OR BUSINESS* PERSON FILING COMPLAINT: Dan Bell 605-231-0328
COMPANY: MidContinent Communications ADDRESS 3507 S. Duluth, Sioux Falls, SD PHONE NUMBER 605-274-8531
SIGNATURE OF COMPLAINANT: Dan Bell DATE: 6-16-03 EMAIL ADDRESS: danb@sio.midco.net

*If the complaint is filed on behalf of a Company, the person signing this form should have the proper authority to file the complaint.

II. ACTION REQUESTED AGAINST:

NAME OF EXCAVATOR/FACILITY OPERATOR: Gleason Tree Company PHONE NUMBER: (605) 368-2678
ADDRESS: 27226 471st Avenue, Harrisburg, SD 57032
WAS A LOCATE REQUESTED FROM SD ONE CALL? YES NO
LOCATE TICKET #: 031630327, 031630329, 031630331, 031630333, 031630335
START DATE ON TICKET: June 16, 2003
DID EXCAVATOR WAIT UNTIL THE START DATE/TIME ON THE TICKET BEFORE COMMENCING EXCAVATION? YES NO
WERE BURIED FACILITIES EXPOSED BY HAND OR WITH NON-INVASIVE EQUIPMENT PRIOR TO EXCAVATION? YES NO

III. FACILITY INVOLVED (IF ANY)

TYPE OF FACILITY INVOLVED: Communications OPERATOR OF FACILITY: Midcontinent Communications
OPERATOR ADDRESS: 3507 S. Duluth, Sioux Falls, SD PHONE NUMBER: 605-274-8531
DEPTH OF COVER: 28" PRESSURE: VOLTAGE: NUMBER OF CABLE PAIRS: 1

IV. MARKING

WERE FACILITIES MARKED? YES NO
WAS THE MARKING COMPLETE PRIOR TO THE START TIME ON THE TICKET? Not Applicable
DID EXCAVATOR PRE-MARK WITH WHITE PAINT? YES NO
WAS THE FACILITY MARKED ACCURATELY (WITHIN 18 INCHES)? Not Applicable
DID EXCAVATOR USE REASONABLE CARE TO MAINTAIN LOCATE MARKS FOR LIFE OF PROJECT? Not Applicable
HAVE YOU DISCUSSED THE PREVIOUS STATEMENTS WITH THE OTHER PARTY? YES NO
IS THERE AGREEMENT? YES NO
IF NO, PLEASE EXPLAIN:

V. DAMAGE (IF ANY)

FATALITIES: INJURIES: LENGTH OF HOSPITALIZATION:
ESTIMATED PROPERTY DAMAGE (\$): NUMBER OF CUSTOMERS AFFECTED:
DAMAGED IN: PUBLIC PRIVATE (RIGHT-OF-WAY)
PHOTOS OF THE DAMAGED FACILITY? YES NO
ADDITIONAL INFORMATION:

VI. PROBABLE VIOLATION

SPECIFIC STATUE(S) OR RULE(S) THAT WAS VIOLATED:
SDCL 49-7A-5 Notification of Proposed Excavation. Work was completed prior to the start date and time on the ticket
SDCL 49-7A-19 Penalties for Intentional Violations
SDCL 49-7A-20 Each Violation as a Separate Offense
ADDRESS/LOCATION OF PROBABLE VIOLATION: 7501 Peregrine Place, 7505 Peregrine Place, 7507 Peregrine Place, 7511
Peregrine Place, 7513 Peregrine Place
DATE/TIME OF PROBABLE VIOLATION: June 13, 2003 at approximately 2:33 PM
HAVE YOU DISCUSSED THIS PROBABLE VIOLATION WITH THE PARTY THE ACTION IS FILED AGAINST: YES
NO
IF YES, NAME OF THE PARTY WITH WHOM YOU DISCUSSED THE PROBABLE VIOLATION:
DESCRIPTION OF PROBABLE VIOLATION:
Excavation activity was completed prior to the start date (6/16/03). Work completed on June 13, 2003 at 2:35 PM
I had contact with the equipment operator on Thursday, June 12, 2003, and advised him that he was digging in advance of the
start date and time on the locate request.

LOCATE

STATE: SD
CDC: SFC

TICKET: 031630335 SEQUENCE: 0151
MAP REF: UPDATE OF:

Transmitted Date: 06/12/2003 Time: 1209 CDT
Prepared Date: 06/12/2003 Time: 1202 CDT

RECEIVED

JUN 19 2003

SOUTH DAKOTA PUBLIC
UTILITIES COMMISSION

LOCATION INFORMATION:

County: LINCOLN City: SIOUX FALLS
Address: 7501 PEREGRINE
Nearest Intersecting Street: 84TH ST

City Limits Legal Given:
Twp: Rng: Sect-Qtr:
Twp: Rng: Sect-Qtr:
Explosives: N Tunnel/Bore: N Depth: 6FT R.O.W.: N
Corner Lot: Front: Rear:

Type of Work: PLANTING TREES
Extent of Work:

;
;
;
;

Location of Work:
MARK THE BACK YARD.

Start Date: 06/16/2003 Time: 1202 CDT Dur: 07 DAYS
Best Time to Call: 0800 - 0800 Meeting Required: N
Work Being Done For: PINACLE VENTURE

Remarks:
EXPIRATION DATE 07-JUL-03

EXCAVATOR INFORMATION:

Company: GLEASON TREE COMPANY
Address: 27226 471ST AVE
City: HARRISBURG, SD 57032
Phone: 605-368-2678 Fax: 605-368-5606
Contact: ARNOLD GLEASON Phone: 605-368-2678
Alt Contact: ARNOLD GLEASON Phone: 605-360-3048

OPERATORS NOTIFIED:

ATT=/AT&T / DAT=/PRAIRIEWAVE / LCR=/LINCOLN RRL WTR/
M08=/MEC-SIOUX FALLS/ NN1=/N NATURAL GAS / NSP=/XCEL ENERGY /
SFA=/SIOUX FALLS WTR/ SFC=/MCC SIOUX FALLS/ UWS=/US WEST-ULS /

TECH COMMENTS:

*already done
184
6-13-3*

LOCATE

STATE: SD

CDC: SFC

TICKET: 031630333

SEQUENCE: 0149

MAP REF:

UPDATE OF:

Transmitted Date: 06/12/2003 Time: 1209 CDT

Prepared Date: 06/12/2003 Time: 1201 CDT

RECEIVED

JUN 19 2003

SOUTH DAKOTA PUBLIC UTILITIES COMMISSION

LOCATION INFORMATION:

County: LINCOLN

City: SIOUX FALLS

Address: 7505 PEREGRINE

Nearest Intersecting Street: 84TH S

City Limits Legal Given:

Twp: Rng: Sect-Qtr:

Twp: Rng: Sect-Qtr:

Explosives: N Tunnel/Bore: N Depth: 6FT R.O.W.: N

Corner Lot: Front: Rear:

Type of Work: PLANTING TREES

Extent of Work:

;
;
;
;

Location of Work:

MARK THE BACK YARD.

Start Date: 06/16/2003 Time: 1200 CDT Dur: 07 DAYS

Best Time to Call: 0800 - 0800 Meeting Required: N

Work Being Done For: PINACLE VENTURE

Remarks:

EXPIRATION DATE 07-JUL-03

EXCAVATOR INFORMATION:

Company: GLEASON TREE COMPANY

Address: 27226 471ST AVE

City: HARRISBURG, SD 57032

Phone: 605-368-2678 Fax: 605-368-5606

Contact: ARNOLD GLEASON

Phone: 605-368-2678

Alt Contact: ARNOLD GLEASON

Phone: 605-360-3048

OPERATORS NOTIFIED:

ATT=/AT&T / DAT=/PRAIRIEWAVE / LCR=/LINCOLN RRL WTR/

M08=/MEC-SIOUX FALLS/ NN1=/N NATURAL GAS / NSP=/XCEL ENERGY /

SFA=/SIOUX FALLS WTR/ SFC=/MCC SIOUX FALLS/ UWS=/US WEST-ULS /

TECH COMMENTS:

*already done
184
6-13-2*

LOCATE

STATE: SD
CDC: SFC
TICKET: 031630331 SEQUENCE: 0148
MAP REF: UPDATE OF:
Transmitted Date: 06/12/2003 Time: 1209 CDT
Prepared Date: 06/12/2003 Time: 1200 CDT

RECEIVED

JUN 19 2003

SOUTH DAKOTA PUBLIC
UTILITIES COMMISSION

LOCATION INFORMATION:

County: LINCOLN City: SIOUX FALLS
Address: 7507 PEREGRINE
Nearest Intersecting Street: 84TH ST

City Limits Legal Given:
Twp: Rng: Sect-Qtr:
Twp: Rng: Sect-Qtr:
Explosives: N Tunnel/Bore: N Depth: 6FT R.O.W.: N
Corner Lot: Front: Rear:

Type of Work: PLANTING TREES
Extent of Work:

,
,
,
,
,

Location of Work:
MARK THE BACK YARD.

Start Date: 06/16/2003 Time: 1159 CDT Dur: 07 DAYS
Best Time to Call: 0800 - 0800 Meeting Required: N
Work Being Done For: PINACLE VENTURE

Remarks:
EXPIRATION DATE 07-JUL-03

EXCAVATOR INFORMATION:

Company: GLEASON TREE COMPANY
Address: 27226 471ST AVE
City: HARRISBURG, SD 57032
Phone: 605-368-2678 Fax: 605-368-5606
Contact: ARNOLD GLEASON Phone: 605-368-2678
Alt Contact: ARNOLD GLEASON Phone: 605-360-3048

OPERATORS NOTIFIED:

ATT=/AT&T / DAT=/PRAIRIEWAVE / LCR=/LINCOLN RRL WTR/
M08=/MEC-SIOUX FALLS/ NN1=/N NATURAL GAS / NSP=/XCEL ENERGY /
SFA=/SIOUX FALLS WTR/ SFC=/MCC SIOUX FALLS/ UWS=/US WEST-ULS /

TECH COMMENTS:

*already done
#184
6-13-3*

LOCATE

STATE: SD

CDC: SFC

TICKET: 031630329

SEQUENCE: 0147

MAP REF:

UPDATE OF:

Transmitted Date: 06/12/2003 Time: 1209 CDT

Prepared Date: 06/12/2003 Time: 1158 CDT

RECEIVED

JUN 19 2003

SOUTH DAKOTA PUBLIC UTILITIES COMMISSION

LOCATION INFORMATION:

County: LINCOLN

City: SIOUX FALLS

Address: 7511 PEREGRINE

Nearest Intersecting Street: 84TH ST

City Limits Legal Given:

Twp: Rng: Sect-Qtr:

Twp: Rng: Sect-Qtr:

Explosives: N Tunnel/Bore: N Depth: 6FT R.O.W.: N

Corner Lot: Front: Rear:

Type of Work: PLANTING TREES

Extent of Work:

,
,
,
,
,

Location of Work:

MARK THE BACK YARD.

Start Date: 06/16/2003 Time: 1157 CDT Dur: 07 DAYS

Best Time to Call: 0800 - 0800 Meeting Required: N

Work Being Done For: PINACLE VENTURE

Remarks:

EXPIRATION DATE 07-JUL-03

EXCAVATOR INFORMATION:

Company: GLEASON TREE COMPANY

Address: 27226 471ST AVE

City: HARRISBURG, SD 57032

Phone: 605-368-2678 Fax: 605-368-5606

Contact: ARNOLD GLEASON Phone: 605-368-2678

Alt Contact: ARNOLD GLEASON Phone: 605-360-3048

OPERATORS NOTIFIED:

ATT=/AT&T / DAT=/PRAIRIEWAVE / LCR=/LINCOLN RRL WTR/

M08=/MEC-SIOUX FALLS/ NN1=/N NATURAL GAS / NSP=/XCEL ENERGY /

SFA=/SIOUX FALLS WTR/ SFC=/MCC SIOUX FALLS/ UWS=/US WEST-ULS /

TECH COMMENTS:

*already done
#184
6-13-3*

LOCATE

STATE: SD

CDC: SFC

TICKET: 031630327

SEQUENCE: 0145

MAP REF:

UPDATE OF:

Transmitted Date: 06/12/2003 Time: 1208 CDT

Prepared Date: 06/12/2003 Time: 1157 CDT

LOCATION INFORMATION:

County: LINCOLN

City: SIOUX FALLS

Address: 7513 PEREGRINE

Nearest Intersecting Street: 84TH ST

City Limits Legal Given:

Twp: Rng: Sect-Qtr:

Twp: Rng: Sect-Qtr:

Explosives: N Tunnel/Bore: N Depth: 6FT

R.O.W.: N

Corner Lot: Front: Rear:

Type of Work: PLANTING TREES

Extent of Work:

,
,
,
,
,

Location of Work:

MARK THE BACK YARD.

Start Date: 06/16/2003 Time: 1152 CDT Dur: 07 DAYS

Best Time to Call: 0800 - 0800 Meeting Required: N

Work Being Done For: PINACLE VENTURE

Remarks:

EXPIRATION DATE 07-JUL-03

EXCAVATOR INFORMATION:

Company: GLEASON TREE COMPANY

Address: 27226 471ST AVE

City: HARRISBURG, SD 57032

Phone: 605-368-2678 Fax: 605-368-5606

Contact: ARNOLD GLEASON

Phone: 605-368-2678

Alt Contact: ARNOLD GLEASON

Phone: 605-360-3048

OPERATORS NOTIFIED:

ATT=/AT&T / DAT=/PRAIRIEWAVE / LCR=/LINCOLN RRL WTR/

M08=/MEC-SIOUX FALLS/ NN1=/N NATURAL GAS / NSP=/XCEL ENERGY /

SFA=/SIOUX FALLS WTR/ SFC=/MCC SIOUX FALLS/ UWS=/US WEST-ULS /

TECH COMMENTS:

*already done
#184
6-13-03*

RECEIVED

JUN 19 2003

**SOUTH DAKOTA PUBLIC
UTILITIES COMMISSION**