



TWO SIDED FORM,
SIGNATURE REQUIRED
ON BACK.

Date of Damage: 12/4/09
Date of Report: 12/7/09

UTILITY DAMAGE REPORT

Watertown Municipal Utilities - 901 4th Ave. S.W. - Watertown, SD 57201 - (605)882-6233

LOCATION INFORMATION

Address/Location of Damage: 20th Ave SE.

Approx. Time of Damage: 4:40 A.M. or (P.M.) Locator(s) Name(s): BW, TR, SS

Time Called to Damage: 4:45 A.M. or (P.M.)

South Dakota One-Call Ticket Number: N/A Attach Copy

Police Report Number: (if applicable) _____

Questions regarding Damage

1. Was There a South Dakota One Call Ticket Called in by Excavator?	YES	<u>(NO)</u>
2. Did Any Part of the Excavation Occur Prior to One Call Ticket Start Time?	<u>(YES)</u>	NO
3. Was Work Area Flagged or Painted by Excavator Prior to Locating?	YES	<u>(NO)</u>
4. Was There Photos Taken of Damage Area?	<u>(YES)</u>	NO
5. Was Utility Hand Exposed?	YES	<u>(NO)</u>
6. Was Utility Locates within 18" of Damage?	YES	<u>(NO)</u>
7. Was There Communication with Excavator about One Call Ticket before Locating?	YES	<u>(NO)</u>

No locate request

Name of employee(s) involved: Jerry Burus, Aaron Erickson, Scott Struss, Bryan Warberg

Excavator Contact Information:

Granggaard Construction Inc
1712 7th Ave NE
Watertown SD 57201
605-886-0559


Picture Information:

Who Took Photos? BW Number of Photos Taken 5

Location of Photos Stored M:\Util Damage\ Granggaard 20th Ave Gas Line

Diagram the Utility Damage

North



South

Describe the Damage Accident in Detail

Damage was to 4" Hp & Tracer wire. The 4" Hp main was scraped but not cut & the tracer wire was cut & stretched. Derrick with Bowis Const. informed us of the damage. Grandgard Construction was the damaging party and was not present on our arrival. No locate had ever been requested by Grandgard on this project

Signatures

[Signature] 12/7/09
Utility Representative Signature and Date

[Signature] 12/7/09
Supervisor's or Forman's signature and date

Bryan Wargong
Printed Name

Mark Mercer
Printed Name

Notes:
