

ONE CALL COMPLAINT FORM
South Dakota Public Utilities Commission
500 East Capitol Avenue
Pierre, Sd 57501-5070

COMPLAINT

Allegation of Probable Violation(s) of South Dakota One Call Laws

Received On June 13, 2012 7:57 am

I. ACTION REQUESTED BY:

COMPLAINT FILED BY: Company

PERSON FILING COMPLAINT: John Brooks

COMPANY: Charles Mix Electric Inc.

ADDRESS: 440 Lake St. Lake Andes , S.D.

PHONE NUMBER: (605) 487-7321

EMAIL: jbrooks@cme.coop

DATE: June 13, 2012

ii. ACTION REQUESTED AGAINST:

NAME OF EXCAVATOR/FACILITY OPERATOR: Wagner Building & Supply

PHONE NUMBER: (605) 384-3654

ADDRESS: Wagner S.D.

WAS A LOCATED REQUESTED FROM SD ONE CALL? Yes

LOCATE TICKET#: 121570507

START DATE ON TICKET: June 7, 2012

DID EXCAVATOR WAIT UNTIL THE START DATE/TIME ON THE TICKET BEFORE COMMENCING EXCAVATION? No

WERE BURIED FACILITIES EXPOSED BY HAND OR NON-INVASIVE EQUIPMENT PRIOR TO EXCAVATION? No

III. FACILITY INVOLVED (IF ANY)

TYPE OF FACILITY INVOLVED:

OPERATOR OF FACILITY:

OPERATOR ADDRESS:

PHONE NUMBER:

DEPTH OF COVER:

PRESSURE:

VOLTAGE:

NUMBER OF CABLE REPAIRS:

IV. MARKING

WERE FACILITIES MARKED? No

WAS THE MARKING COMPLETE PRIOR TO THE START TIME ON THE TICKET? Yes

DID EXCAVATOR PRE-MARK WITH WHITE PAINT? No

WAS THE FACILITY ACCURATELY MARKED (WITHIN 18 INCHES)? Yes

DID EXCAVATOR USE REASONABLE CARE TO MAINTAIN LOCATE MARKS FOR LIFE OF PROJECT? No

HAVE YOU DISCUSSED THE PREVIOUS STATEMENTS WITH THE OTHER PARTY? No

IS THERE AGREEMENT? No

IF NO, PLEASE EXPLAIN:

V. DAMAGE (IF ANY)

FATALITIES: 0

INJURIES: 0

LENGTH OF HOSPITALIZATION:

ESTIMATED PROPERTY DAMAGE:

NUMBER OF CUSTOMERS AFFECTED:

DAMAGED IN:

PHOTOS OF THE DAMAGED FACILITY: No

ADDITIONAL INFORMATION: I received the locate mid morning on the 5th-- Received a call from the Phone company approx. 1/2 hour later, they had been out to locate, as they were leaving Wagner Building was starting to dig, they new we hadn't been there yet.

VI. PROBABLE VIOLATION

SPECIFIC STATUE(S) OR RULE(S) THAT WAS VIOLATED: Digging well before the 48 hrs.

ADDRESS/LOCATION OF PROBABLE VIOLATION: 299th St. X 391st ave. 1/2 mile E. Both sides of 299th

DATE/TIME OF PROBABLE VIOLATION: June 5, 2012 10:00 am

HAVE YOU DISCUSSED THE PROBABLE VIOLATION WITH THE PARTY THE ACTION IS FILED AGAINST? False

IF YES, NAME THE PARTY WITH WHOM YOU DISCUSSED THE PROBABLE VIOLATION:

DESCRIPTION OF PROBABLE VIOLATION: This is the first complaint I've filed, but this not the first time Wagner Building has put in a locate and started digging before the 48 hrs.

South Dakota One Call SEQUENCE NUMBER 6 CDC = MIX

Type: *** ROUTINE ***

Transmit: 06/05/12 At: 1345
Prepared: 05-JUN-12 Time: 1339 By: Maria B
Ticket No.: 121570507

Operators Notified:
FRT=/FORT RANDALL.../ MIX=/CHARLES MIX .../ RAN=/RANDALL COMM.../

Excavator Information:

Caller: JAY WUNDER Phone: (605) 384-3654
Excavator: WAGNER BUILDING & SUPPLY
Address: 39379 SD HWY 46
City: WAGNER, SD 57380
Phone: 605-384-3654 Fax: 605-384-5935
Email: JWUNDER@WBSI.BIZ
Contact: JAY WUNDER Phone: 605-384-3654
Alt. Contact: Phone: 605-384-3654

Location Information:

County: CHARLES MIX City/Village: WAGNER

Map Ref: 43028098210A Grids: 35
Exc. Site Address: 0 299TH ST
Nearest Intersection: 391ST AVE
Type of Work : REPLACING CULVERT
Work Being Done For: HIGHLAND TWP
Depth: 04 FEET Explosives: N Tunnel/Bore: N
Start Date: 06/07/12 Time: 1345 Duration: 1 DAY
Meeting Required: N Best Time to Contact: 0800 - 1700
Exc. Site (Marking Instr.): R.O.W.: Y TRSQ:
GPS Lat/Long:
Remarks and Driving Directions:
FROM 299TH ST & 391ST AVE GO APPX 0.5 MI E ON 299TH ST TO HOLE IN
RD, MARK ACROSS THE RD FROM FENCE LINE TO FENCE LINE, STAYING
W/IN 20 FT OF BOTH SIDES OF RD
Expires On: 6/28/2012 1:45:25 PM

End Ticket

M
Wagner