
From: donotreply@sdonecall.com[SMTP:DONOTREPLY@SDONECALL.COM]

Sent: Wednesday, July 10, 2013 12:01:19 PM

To: PUC Docket Filings

Subject: New One Call Complaint Form

Auto forwarded by a Rule

1. Action Requested By:

Complaint filed on behalf of or by: MIDAMERICAN ENERGY COMPANY

Contact Person: SILICIA BOUTCHEE

Phone: 515-252-6906 **Ext:**

Street Address or PO Box: 3500 104TH ST

City: URBANDALE

State: IA

Zip: 50322

Fax: 515-242-3962

Email Address: JJBOUTCHEE@MIDAMERICAN.COM

Date: 7/10/2013

2. Action Requested Against:

Name of excavator / facility operator: SELECT BUILDERS

Phone: 605-214-1295 **Ext:**

Street Address Or PO Box: 47104 TALLGRASS CIR

City: HARRISBURG

State: SD

Zip: 57032

Fax: --

Email Address:

Is this party aware of your allegations?: Yes

Provide detail including whom you spoke with: SAM WIPF WITH SELECT BUILDERS ADVISED CREW ONSITE HIT A GAS LINE WHILE INSTALLING A MAILBOX, NOT SURE IF THEY DID A LOCATE

3. Basic Facts:

Street Address / location of alleged violation: 738 E EL DORADO

City: SIOUX FALLS

State: SD

Date of alleged violation: 04/18/2013

Time of alleged violation: 9:28 a.m.

Describe your allegation: SELECT BUILDERS WAS USING A AUGER TO INSTALL MAILBOX AND HIT A PLASTIC GAS SERVICE.

Do you believe the alleged violation to be intentional?: Not Sure

Why or why not?: NO LOCATES REQUESTED BY SELECT BUILDERS - THERE WERE SOME OLD FLAGS VISABLE FROM PREVIOUS LOCATE CALLED IN BY ANOTHER CONTRACTOR, WHICH WERE ACCURATE

4. Excavation / Locate Information:

Was a locate requested from SD One Call?: No

If a locate was requested:

Locate ticket #:

Start date and time on ticket:

Did the excavator wait until the start date / time on the ticket before commencing excavation?: No

If no, when did excavation begin (date and time)?: 04/18/2013

Did the excavator maintain a minimum horizontal clearance of 18 inches between a marked facility and mechanical equipment?: NA

Explain:

Were buried facilities exposed by hand or non-invasive equipment prior to excavation?: NA

Were facilities marked?: NA

Was the marking complete prior to the start time on the ticket?: NA

Did the excavator pre-mark with white paint?: No

Was the facility marked accurately (within 18 inches)?: NA

Did the excavator use reasonable care to maintain locate marks for the life of project?: NA

Type of facility involved: PLASTIC GAS LINE

Operator of facility (if known): MIDAMERICAN ENERGY COMPANY

Operator address (Street or PO Box): 3500 104TH ST

City: URBANDALE

State: IA

Zip: 50322

Phone: 515-252-6906

Depth of Cover: 36"

Pressure: 48#

Voltage: N/A

of cable pairs: N/A

5. Damages

Was the facility damaged?: Yes

If yes, provide detail and an estimate of damage: REPLACED 2 COUPLINGS AND 1' OFF PLASTIC PIPE- LABOR 681.72, FLEET-89.76, MATERIAL 15.19, TOTAL \$786.67

Were damages on public right of way or private property?: Public

Was anyone injured as a result of facility damage?: No

If yes, provide detail:

Length of hospitalization:

Were there fatalities?: No

If yes, provide detail:

Was operator service affected?: No

If yes, provide detail (how many customers for how long):

Other information regarding injuries or damages:

6. Statutory Violation

Specific statute(s) or rule(s) you believe were violated: 49-7A-5 & 49-7A-10

Other information to support your position: EMERGENCY TICKET CALLED IN BY MEC FOR REPAIRS - 131080074- 4/18/13 @ 0951