Picture Taken 8-23-13
open trench & Back Hoe
Fink Excavation

Picture Taken
8-23-13
service valve
water line
32'
2" m.d Dakota
water distribution line

Picture Taken
8-23-13
meter pit
water line
service valve

Picture Taker
8-23-13

Picture Taken
8-23-13
Mid Dakotah water line