
From: donotreply@sdonecall.com[SMTP:DONOTREPLY@SDONECALL.COM]

Sent: Thursday, October 10, 2013 3:59:55 PM

To: PUC Docket Filings

Subject: New One Call Complaint Form

Auto forwarded by a Rule

1. Action Requested By:

Complaint filed on behalf of or by: MIDAMERICAN ENERGY COMPANY

Contact Person: SILICIA BOUTCHEE

Phone: 800-275-5745 **Ext:**

Street Address or PO Box: 3500 104TH ST

City: URBANDALE

State: IA

Zip: 50322

Fax: 515-242-3962

Email Address: DAMAGECLAIMS@MIDAMERICAN.COM

Date: 10/10/2013

2. Action Requested Against:

Name of excavator / facility operator: ANKENY CONSTRUCTION

Phone: 605-651-9351 **Ext:**

Street Address Or PO Box: 3212 PENINAH ST

City: YANKTON

State: SD

Zip: 57078

Fax: --

Email Address: Ankpadi@gmail.com

Is this party aware of your allegations?: Yes

Provide detail including whom you spoke with: Yes- Sent invoice for damages

3. Basic Facts:

Street Address / location of alleged violation: 3702 STACI LANE

City: YANKTON

State: SD

Date of alleged violation: 07/12/2013

Time of alleged violation: 2:01 p.m.

Describe your allegation: Contractor hit 1/2" plastic gas line with a re-rod stake while installing forms for concrete parking pad.

Do you believe the alleged violation to be intentional?: Not Sure

Why or why not?: No locates

4. Excavation / Locate Information:

Was a locate requested from SD One Call?: No

If a locate was requested:

Locate ticket #:

Start date and time on ticket:

Did the excavator wait until the start date / time on the ticket before commencing excavation?: No

If no, when did excavation begin (date and time)?:

Did the excavator maintain a minimum horizontal clearance of 18 inches between a marked facility and mechanical equipment?: NA

Explain: No locate called in before excavating

Were buried facilities exposed by hand or non-invasive equipment prior to excavation?: No

Were facilities marked?: No

Was the marking complete prior to the start time on the ticket?: NA

Did the excavator pre-mark with white paint?: No

Was the facility marked accurately (within 18 inches)?: NA

Did the excavator use reasonable care to maintain locate marks for the life of project?: No

Type of facility involved: gas

Operator of facility (if known): MidAmerican Energy Company

Operator address (Street or PO Box): 3500 104th St

City: Urbandale

State: IA

Zip: 50322

Phone: 800-275-5745

Depth of Cover: 18"

Pressure: 45lbs

Voltage:

of cable pairs:

5. Damages

Was the facility damaged?: Yes

If yes, provide detail and an estimate of damage: \$344.81 - Labor, \$55.37-fleet, \$7.29- Material-
TOTAL=407.47

Were damages on public right of way or private property?: Public

Was anyone injured as a result of facility damage?: No

If yes, provide detail:

Length of hospitalization:

Were there fatalities?: No

If yes, provide detail:

Was operator service affected?: Yes

If yes, provide detail (how many customers for how long): 1 customer affected

Other information regarding injuries or damages:

6. Statutory Violation

Specific statute(s) or rule(s) you believe were violated: 49-7A-5 & 49-7A-10

Other information to support your position: Ankeny Construction called in a Damage ticket #131930428 (attached)