



USIC LOCATING SERVICES, INC.

Notification Report

38020130712001

FBI Report

57078

Fact Based Investigation Report

Notification ID	38020130712001	District	South Dakota
Damage Date	07/12/2013 12:30	Notification Date	07/12/2013 15:55
Notified By	EMIAL (Facility Owner)		
Damage Address	3702 STACI LANE YANKTON, SD		

Damaged Customer Mid American Energy Company - SD

Investigation Date From 07/12/2013 14:00:00 To 07/12/2013 14:15:00

Excavator Involved ANKENY CONSTRUCTION
Type of Excavation parking lot

Orig. Locate Request	Start Date
Type of Ticket	Locate Req. Info N/A

Damage Request # 131930428 Start Date 07/12/2013 16:00

Pictures Taken By	none	Date	07/12/2013 16:00
Photography Type	Digital	Frame #	

Investigator Emp. # 001794 Investigator Name Dale Myers
Based on your investigation, is further investigation needed? No

Fact Based Investigation Customer Information

Facility Description	Low Profile	Facility ID	service - 1/2"
Locator Name & EMP #	Haki Brian - 136518	Locator	Not Known

Investigation Findings
 No Locate Req. By Contractor
 Old Request
 Other

Other Notes
1-10

Investigation Methods
Visual, Facility Exposed At Time Of Investigation

Investigator Statement/Causal Factors

no marks remain. Name: BRADIE A HENDRIX Address: 3702 STACI LN City / State / Zip: YANKTON, SD -
 Description: hit gas line- Kevin waiting at site. Driving Re-Bar into ground just now & nicked gas line,
 blowing gas, strong gas odor, no injuries, no emergency service called, doesnt have dig#

Names of Utility Representatives Contacted or on Site and Statement

billing contractor

Names of Excavator's Representatives Contacted or on Site and Statement

none

Other individuals on site

none

Were any markings visible on the damage site upon arrival? No
 Were any other indicators of facility present in the area? Yes
 Was the excavation within the tolerance zone of marks? No
 Extent of facility damage drove stake into service
 Replacement Footage 3'
 Was contractor assistance required? If yes, who? No
 What contractor equipment was used? splicer
 Is the facility shown on the utility records? Yes
 If yes, list record numbers Gt Viewer