
From: donotreply@sdonecall.com[SMTP:DONOTREPLY@SDONECALL.COM]

Sent: Friday, October 11, 2013 10:02:40 AM

To: PUC Docket Filings

Subject: New One Call Complaint Form

Auto forwarded by a Rule

1. Action Requested By:

Complaint filed on behalf of or by: MidAmerican Energy Company

Contact Person: Silicia Boutchee

Phone: 800-275-5745 **Ext:**

Street Address or PO Box: 3500 104th st

City: Urbandale

State: IA

Zip: 50322

Fax: 515-242-3962

Email Address: Damageclaims@midamerican.com

Date: 10/11/2013

2. Action Requested Against:

Name of excavator / facility operator: First Dakota Horticulture

Phone: 605-728-5182 **Ext:**

Street Address Or PO Box: 46551 264th St

City: Sioux Falls

State: SD

Zip: 57107

Fax: --

Email Address:

Is this party aware of your allegations?: Yes

Provide detail including whom you spoke with: Received invoice for damages- no locates called in

3. Basic Facts:

Street Address / location of alleged violation: 221 S 6th Ave

City: Brandon

State: SD

Date of alleged violation: 08/13/2013

Time of alleged violation: 9:00 a.m.

Describe your allegation: First Dakota Horticulture was replacing tree in yard and hit plastic gas service with hand tools.

Do you believe the alleged violation to be intentional?: Not Sure

Why or why not?: No Locates called in prior to excavating

4. Excavation / Locate Information:

Was a locate requested from SD One Call?: No

If a locate was requested:

Locate ticket #:

Start date and time on ticket:

Did the excavator wait until the start date / time on the ticket before commencing excavation?: No

If no, when did excavation begin (date and time)?: 08/13/2013 8:00 a.m.

Did the excavator maintain a minimum horizontal clearance of 18 inches between a marked facility and mechanical equipment?: NA

Explain: No Locates

Were buried facilities exposed by hand or non-invasive equipment prior to excavation?: NA

Were facilities marked?: NA

Was the marking complete prior to the start time on the ticket?: NA

Did the excavator pre-mark with white paint?: No

Was the facility marked accurately (within 18 inches)?: NA

Did the excavator use reasonable care to maintain locate marks for the life of project?: NA

Type of facility involved: 1/2" Plastic gas line

Operator of facility (if known): MidAmerican Energy Company

Operator address (Street or PO Box): 3500 104th St

City: Urbandale

State: IA

Zip: 50322

Phone: 800-275-5745

Depth of Cover: 24"

Pressure: 48#

Voltage:

of cable pairs:

5. Damages

Was the facility damaged?: Yes

If yes, provide detail and an estimate of damage: Replaced 1' of plastic gas line- Labor-\$611.01, fleet-\$56.15, materials-\$15.71 Total= \$682.87

Were damages on public right of way or private property?: Public

Was anyone injured as a result of facility damage?: No

If yes, provide detail:

Length of hospitalization:

Were there fatalities?: No

If yes, provide detail:

Was operator service affected?: Yes

If yes, provide detail (how many customers for how long): 1 customer affected

Other information regarding injuries or damages:

6. Statutory Violation

Specific statute(s) or rule(s) you believe were violated: 49-7A-5 & 49-7A-10

Other information to support your position: Emergency ticket was called in by MEC for repairs-
132250188- 8/13/13 @ 9:17am