
From: donotreply@sdonecall.com[SMTP:DONOTREPLY@SDONECALL.COM]

Sent: Friday, October 11, 2013 10:44:17 AM

To: PUC Docket Filings

Subject: New One Call Complaint Form

Auto forwarded by a Rule

1. Action Requested By:

Complaint filed on behalf of or by: MidAmerican Ebergy Company

Contact Person: Silicia Boutchee

Phone: 800-275-5745 **Ext:**

Street Address or PO Box: 3500 104th St

City: Urbandale

State: IA

Zip: 50322

Fax: 515-242-3962

Email Address: Damageclaims@midamerican.com

Date: 10/11/2013

2. Action Requested Against:

Name of excavator / facility operator: Aaron George

Phone: 605-759-2631 **Ext:**

Street Address Or PO Box: 710 S Prairie Ave

City: Tea

State: SD

Zip: 57064

Fax: --

Email Address:

Is this party aware of your allegations?: Yes

Provide detail including whom you spoke with: Invoiced for damages- no locates

3. Basic Facts:

Street Address / location of alleged violation: 313 N Minnestoa Ave

City: Sioux Falls

State: SD

Date of alleged violation: 07/24/2013

Time of alleged violation: 7:45 p.m.

Describe your allegation: Pulled gas service out of gas main with skid loader- no locates requested prior to excavation

Do you believe the alleged violation to be intentional?: Not Sure

Why or why not?: No Locates

4. Excavation / Locate Information:

Was a locate requested from SD One Call?: No

If a locate was requested:

Locate ticket #:

Start date and time on ticket:

Did the excavator wait until the start date / time on the ticket before commencing excavation?: No

If no, when did excavation begin (date and time)?: 07/24/2013

Did the excavator maintain a minimum horizontal clearance of 18 inches between a marked facility and mechanical equipment?: NA

Explain: Aaron Gearge did not call in locates - no hand digging, damage caused by skidloader

Were buried facilities exposed by hand or non-invasive equipment prior to excavation?: No

Were facilities marked?: No

Was the marking complete prior to the start time on the ticket?: NA

Did the excavator pre-mark with white paint?: No

Was the facility marked accurately (within 18 inches)?: NA

Did the excavator use reasonable care to maintain locate marks for the life of project?: NA

Type of facility involved: Gas Service and Gas Main

Operator of facility (if known): MidAmerican Energy Company

Operator address (Street or PO Box): 3500 104th St

City: Urbandale

State: IA

Zip: 50322

Phone: 800-275-5745

Depth of Cover: 12"

Pressure: 10#

Voltage:

of cable pairs:

5. Damages

Was the facility damaged?: Yes

If yes, provide detail and an estimate of damage: Damage gas line, MEC retired gas service at the service tee-Labor \$4,208.90, Fleet-\$397.54, other- \$983.83 Total = \$5,590.27

Were damages on public right of way or private property?: Public

Was anyone injured as a result of facility damage?: No

If yes, provide detail:

Length of hospitalization:

Were there fatalities?: No

If yes, provide detail:

Was operator service affected?: Yes

If yes, provide detail (how many customers for how long): 1 customer affected

Other information regarding injuries or damages:

6. Statutory Violation

Specific statute(s) or rule(s) you believe were violated: 49-7A-5 & 49-7A-10

Other information to support your position: Emergency ticket called in by MEC for repairs- 132050738 -
7/24/13 @ 8:49pm