

1. ACTION REQUESTED BY

Complaint filed on behalf of or by: Northern Natural Gas Company

Contact Person: James R. Talcott

Phone: (402) 398-7003

Ext: none

Street Address or PO Box: 1111 South 103rd Street

Omaha, Nebraska 68124

United States

Fax: 402-398-7426

Email: jim.talcott@nngco.com

Date: Dec 08, 2015

2. ACTION REQUESTED AGAINST

Name of excavator / facility operator: Lee Feldhaus

Phone:(605) 941-1349

Ext: None

Street Address or PO Box: 204 N. Dakota St.

Howard, South Dakota 57349

United States

Fax:

Email Address:

Is this party aware of your allegations?: Yes

Provide detail including whom you spoke with:

3. BASIC FACTS

Street Address / location of alleged violation:SW 1/4 of Sec 24, T107N, R55W

City: Winfred

State: South Dakota

Date of alleged violation: Dec 03, 2015

Time of alleged violation: 03:39 PM

Describe your allegation: On December 3, 2015, Northern Natural Gas was performing aerial patrol of its Howard branchline and discovered tiling within 500 feet of its 3-inch-diameter Howard branchline. The pipeline was operating at approx. 690 psig at the time. Eagle Sky Patrol dropped warning gloves and the tiler, Lee Feldhaus Contracting, stopped tiling. No one call had been placed.

Do you believe the alleged violation to be intentional?: Yes

Why or why not?: The contractor excavated without first placing a one call.

4. EXCAVATION / LOCATE INFORMATION: if applicable

Was a locate requested from SD One Call?: No

Locate ticket #:

Start date on ticket:

Start time on ticket:

Did the excavator wait until the start date / time on the ticket before commencing excavation?: No

If no or not sure, when did excavation begin (date)?:

If no or not sure, when did excavation begin (time)?:

Did the excavator maintain a minimum horizontal clearance of 18 inches between a marked facility and mechanical equipment?: No

Explain:

Were buried facilities exposed by hand or non-invasive equipment prior to excavation?: No

Were facilities marked?: NA

Was the marking complete prior to the start time on the ticket?: NA

Did the excavator pre-mark with white paint?: No

Was the facility marked accurately (within 18 inches)?: NA

Did the excavator use reasonable care to maintain locate marks for the life of project?: NA

Type of facility involved:

Operator of facility (if known):

Operator address (Street or PO Box:

United States

Operator Phone:

Depth of Cover:

Pressure:

Voltage:

of cable pairs:

5. DAMAGES: (Please provide pictures)

Was the facility damaged?: No

If yes, provide detail and an estimate of damage:

Were damages on public right of way or private property?:

Was anyone injured as a result of facility damage?: No

If yes, provide detail:

Length of hospitalization:

Were there fatalities?: No

If yes, provide detail:

Was operator service affected?: No

If yes, provide detail (how many customers for how long):

6. STATUTORY VIOLATION (if known):

Specific statute(s) or rule(s) you believe were violated: SDCL 49-7A, including 49-7A-5

Other information to support your position: Landowner is Martin Conner, 440th Ave., Winfred, SD 57076

LOCATE TICKETS, PHOTOS, WITNESS STATEMENTS AND ANY OTHER DOCUMENTATION TO SUPPORT YOUR ARGUMENT MUST BE ATTACHED WHEN SUBMITTING THIS FORM.

Attachment #1

Attachment #2

Attachment #3

Attachment #4

Attachment #5

Attachment #6

Attachment #7

Attachment #8

Attachment #9

Attachment #10

2015-12-08 06:39:06