



Bob, on the left from WBI, standing on his pipe.

Kip, on right from MDU, standing on his pipe.

Please note there are no locates marks on Kips.



MDU flags marked with WBI flags.



WBI and MDU flags one paint mark.



MDU exposing gas line.



Correctly marked locates after strike.



exposed gas line showing damage.



Gas line showing extent of damage



Added Fill to increase depth of gas line at my own expense



erosion control in place to protect fill over gas line



Current photo vegetation in place.