

South Dakota One Call Notification Board
PO Box 187
Rapid City, SD 57709

IMPORTANT: This form is provided only as assistance in preparing your South Dakota One Call Complaint. Although it is not required, we encourage you to use this form. Please be as thorough as possible to assist the Enforcement Panel in making its determination. You may include additional information as necessary.

Complaint filed on behalf of or by:	Montana Dakota Utilities
Contact Person:	Don Bohle
Phone	(605) 848-2485
Name or Company Name	Montana Dakota Utilities
Street Address or PO Box	401 Main St Mobridge, South Dakota 57401 United States
Email	don.bohle@mdu.com
Date	May 07, 2021
Name of excavator / facility operator:	R & W Construction
Phone	(605) 295-2996
Name or Company Name	R & W Construction
Street Address or PO Box	2602 Whispering Shores Dr Ft Pierre, South Dakota 57532 United States
Email	bo.RWconstruction@outlook.com
Is this party aware of your allegations?	No
ALL SPECIFIC STATUTES AND ADMINISTRATIVE RULES MUST BE STATED: not sure of exact statute In the Operations Manual for Facility Operators and Excavators in Section IV paragraph 9 it states; ticket not valid for more than twenty one calendar days from the start on the ticket. This ticket was 28 days old.	
Other information to support your position: after 21 days the contractor should have called in for a new locate	
Street Address / location of alleged violation:	610 W Sioux Ave
City	Pierre

State	SD
Date of alleged violation:	May 03, 2021
Time of alleged violation:	11:00 AM
Describe your allegation:	contractor did not call in for a new locate ticket that was over 21 days old
Do you believe the alleged violation to be intentional?	Yes
Why or why not?	they knew the ticket was past the due date
Was a locate requested from SD One Call?	Yes
Locate ticket #:	2109174375
Start date on ticket:	Apr 05, 2021
Start time on ticket:	09:00 AM
Did the excavator wait until the start date / time on the ticket before commencing excavation?	Yes
Did the excavator maintain a minimum horizontal clearance of 18 inches between a marked facility and mechanical equipment?	No
Explain	ticket was called in on 4/1/21 hit line was on 5/3/21
Were buried facilities exposed by hand or non-invasive equipment prior to excavation?	No
Were facilities marked?	Yes
Was the marking complete prior to the start time on the ticket?	Yes
Did the excavator pre-mark with white paint?	NA

Was the facility marked accurately (within 18 inches)?	Yes
Did the excavator use reasonable care to maintain locate marks for the life of project?	No
Type of facility involved:	1.25" gas line
Operator of facility (if known):	montana dakota utilities
Operator address (Street or PO Box):	401 Main St Mobridge, South Dakota 57401 United States
Operator Phone	(605) 848-2485
Depth of Cover (If unsure put N/A)	12"
Pressure: (If none, write none)	40 psi
Voltage: (If none, write none)	none
# of cable pairs: (If none, write none)	none
Was the facility damaged?	Yes
If yes, provide detail and an estimate of damage:	dug through the gas line with backhoe. pictures are on the investigation on the attachment
Were damages on public right of way or private property?	Private
Was anyone injured as a result of facility damage?	No
Were there fatalities?	No
Was operator service affected?	Yes
If yes, provide detail (how many customers for how long):	hit service line feeding one customer. Excess Flow Valve stopped the gas flow after hitting the line

Was the one-call notification center immediately notified of the damage, dislocation, or disturbance? Yes

Was the operator of the facility immediately notified of the damage, dislocation, or disturbance? Yes

Was there an escape of any flammable, toxic, or corrosive gas or liquid? No

Please provide a Fire Department or Emergency Services incident report, if available Not Available

Attachment Information

File names should not include symbols. Example:(\$, &, *, % .) etc.